



<https://www.applefritter.com/content/how-fix-nonstandard-apple-1-video>

BILL OF MATERIALS

For each component min/max value are reported, based on builder's experience. Modifications to values may be needed.

- Q1: PNP Transistor with hfe>125 (i.e. BC558C, BC212B)
- C1: 33pF to 47 pF (220pF also reported to be working on some monitor)
- RA: 5.1 kohm to 20 kohm, 1-5%, 1/4W
- RB: 75 kohm to 100 kohm, 1-5%, 1/4W
- RC: 3.1 kohm to 3.3 kohm, 1-5%, 1/4W

TITLE: APPLE-1 VIDEO FIX		REV: 1.0
Company:		Sheet: 1/1
Date: 2021-12-08	Drawn By: Uncle Bernie	